





MEUBLES

DEMEYERE



SAV
SPAREPARTS
KUNDERDIENST
POST VENTAS
SERVICE NA VERKOOP
SERVIZIO POST-VENDITA
SERVICO DEPOIS DE VENDA
SERWIS POGWARANCYJNY

62608

245195-1



Rep.	Dim.	Qté.
1	597*397	1
2	600*264	2
3	368*263	2
4	368*241	1
5	581*382	1



1H 00 Mn



(FR)

SECURITE

IMPORTANT-A LIRE SOIGNEUSEMENT-A CONSERVER
POUR CONSULTATION ULTERIEURE

(GB)

CAUTION

IMPORTANT-TO BE READED CARREFULY-TO BE
CONSERVED FOR LATER CONSULTATION

(DE)

SICHERHEITSVORSCHRIFTEN

WICHTIG-GENAU DURCHZULESEN-AUFZUBEWAHREN
FÜR SPÄTEREN GEBRAUCH

(ES)

SEGURIDAD

IMPORTANTE-LEER CON ATENCION-CONSERVAR
PARA CONSULTAS POSTERIORES

(NL)

VEILIGHEID

BELANGRIJK-ZORGVULDIGGELEZEN TE WORDEN-BEWAARD
TE WORDEN VOOR LATERE RAADPLEGING

(IT)

SICUREZZA

IMPORTANTE-DA LEGGERE ATTENTAMENTE-DA
CONSERVARE PER CONSULTAZIONE ULTERIORE

(PT)





SEGURANCA

IMPORTANTE-PARA LER COM ATENCAO-PARA
CONSERVAR PARA COOSULTA ULTERIOR

(PL)

UWAGA



WAZNE-UWAZNIE PRZECZYTAC-ZACHOWAC
CELEM POZNIEJSZYCH KONSULTACJI






8930	X1	340750	X8	706	X4	333009	X2	333012	X2
434	X1	949	X4	332124	X1	913	X2	566	X2
569	X2	356725	X1	333016	X2	1107	X8	360689	X4





1	333012	X2	949	X4	8930	X1





2	356725	X1	360689	X4




3	340750	X4	1107	X4	434	X1
						



4	340750	X4	1107	X4	434	X1
						








5	333016	x2
		



6

333009

X2



7

332124


X1

913







X2

706

X4



Ø4



8

566

X2

569

X2

